

# PRODUCT IMPROVEMENT BULLETIN



NUMBER

SD 8/72/5

DATE

March 30th, 1972.

SUBJECT :

Effective on VH/CH vehicles with build date code CC13 and later, a revised ignition steering lock assembly has been introduced.

Improved  
Ignition  
Lock

This lock has wings added to the lock barrel, is easier to operate, more positive in its action and is easier to service.

The following body numbers reflect this improvement.

VH 1E22	1113	VH 1M41	1542	VH 1M45	688
1122	308	2M41	838	2M45	270
3L22	237	3D41	909	3D45	248
3M22	186	3M41	1592	3M45	719
4L22	196	4D41	1945	4D45	545
4M22	121	4M41	1428	4M45	214
8M22	129	4M41	2524	4M45	987
		6P41	1303	6M45	345
4M23	107	7D41	343	7D45	234
6P23	146	7S41	1269	8D45	436
8M23	213	8D41	1161	8M45	554
8P23	143	8M41	2018		
		8P41	1028	VH 1M29	963
CH 8P41	284			3M29	884
6P41	1271			3D29	933
8P23	65			4D29	738
6P23	373			4M29	682
				6H29	735
				7D29	665
				7H29	673
				7S29	950
				8D29	759
				8H29	994

MODELS :

VH/CH

GROUP :

Electrical

*M.G. Aspley*  
M.G. ASPLEY

MANAGER SERVICE TECHNICAL OPERATIONS